

CERTAIN 2021 MODEL YEAR F-150 AND MUSTANG MACH-E VEHICLES WITH FORD CO-PILOT360™ ACTIVE 2.0 PREP PACKAGE (INCLUDES FORD BLUECRUISE PREP KIT) - BLUECRUISE MODULE PROGRAMING

SERVICE PROCEDURE

Module Programming

NEW! 1. From the vehicle settings menu disable the 30 minute max idle option.

- For F-150 vehicles, from the center display press the vehicle settings button and turn off the 30 minute max idle setting. See Figure 1.




FIGURE 1

- For Mach-E vehicles, from the center stack press the vehicle icon in the upper left corner > select the vehicle setting tab > and turn off the vehicle power down setting. See Figure 2.




FIGURE 2



2. Check the vehicle's **State Of Charge Parameter Identification Data (PID)** by performing the following:

- Launch the Ford Diagnostic and Repair System (FDRS) and navigate to toolbox tab > datalogger > BCM and select **BATT SOC PID**.
- Ensure that the **BATT_SOC PID** reads over 80%. If the PID is less than 80%, fully recharge the vehicle's 12-volt battery using the appropriate Rotunda battery tester and charger.
- Remove the charger from the vehicle and using FDRS, navigate to toolbox tab > BCM > **Reset Battery**.
- Monitor Sensor Learned Values application. Perform the BMS reset.
- Connect the Rotunda battery tester and charger and set it to maintain 12.6 to 13.6 volts. Monitor the voltage real time using the indicator at the bottom right corner of FDRS to ensure that it is within this range.

NOTE: Verify that the negative cable of the charger is installed on a chassis or engine ground, and not the 12 volt battery negative terminal to prevent the battery saver mode from activating on the vehicle.

NOTE: If the diagnostic software does not load or if the vehicle cannot be identified properly, make sure there is a good internet connection and the Vehicle Communication Module (VCM) is properly connected to the Data Link Connector (DLC).

NOTE: VCM 3 is recommended for improved data download time.

3. Log into Ford Diagnostic and Repair System (FDRS). Ensure FDRS is updated to the latest version at **34.5.1** or higher.



NEW ! NOTE: A 32GB or larger USB flash drive is required for APIM, TCU, Cluster, and GWM software updates. Make sure the USB flash drive being used is formatted correctly. To see the available drives, hold down the Windows icon keyboard key and press the E keyboard key. Right click on the USB flash drive and select Properties. If File System under the General tab is not exFAT, the drive must be formatted.

- *To format the USB flash drive:*
 - *Right click on the USB flash drive*
 - *Select Format, select exFAT for the File System*
 - *Select Default Allocation Size for the Allocation Unit Size.*
 - *De-selecting Quick Format is not necessary and will result in a lengthier operation.*
- See Figure 3.*




FIGURE 3

4. Start a new FDRS session.

NOTE: Vehicle information is automatically retrieved by the diagnostic software and a Network Test is run. Vehicle identification data appears on the screen when this is complete.

5. Select **Toolbox** tab.



NEW! **STEPS 6 THROUGH 11 WILL BE USED MULTIPLE TIMES DURING STEPS 12 THROUGH 24.**

6. Select **Software Updates** tab to see updates available.

NEW! **7. Select the module from the Module Programming Sequence section below starting at Step 12.**

8. When prompted by the FDRS, connect the USB flash drive to the personal computer (PC).

9. When prompted by the FDRS, safely remove/eject the USB flash drive from the PC, turn the vehicle to Key On Engine Running (KOER), and connect the USB to the media hub to install the software update. The update starts automatically and may take 10 minutes or longer to complete.

NOTE: It may take up to 5 minutes for the vehicle to recognize the USB flash drive with software update.

10. For APIM, TCU, Cluster, and GWM USB software updates when SYNC touchscreen prompts to restart the vehicle:

- Turn the vehicle **OFF**.
- Wait ten minutes.
- Turn the vehicle to KOER.

11. Leave the USB drive inserted into the vehicle, until the vehicles infotainment display screen states **programming successful**.

NOTE: It may take up to 5 minutes before SYNC touchscreen displays Update Successful pop up. After 5 minutes if “Successful” pop up is not shown on SYNC touchscreen, remove the USB and select **YES** on the FDRS “Was the USB Update Successful” prompt (FDRS verifies if the module software update was successfully installed on the module).

NEW! **NOTE: Repeat Steps 6-11 (while performing Steps 12-24) until no more software updates are available for modules covered in Steps 12-24.**

MODULE PROGRAMMING SEQUENCE

IMPORTANT NOTE: Modules need to be programmed in exactly the order as listed below (some are repeated) unless there is no update available. Module updates will vary per vehicle based on Ford Power-UP over-the-air (OTA) updates previously completed. Some modules may already be at the latest level.

12. Select **GWM** - Gateway Module (GWM) – software update.

NEW!

- **See Steps 6-11.**
- Run application.
- If no more software updates are available, move to the next module in the sequence.



NOTE: If FSA 22B08 is open for this vehicle, perform that field action before proceeding.

- NEW !** 13. Select **TCU** - Telematics Control Unit (TCU) - software update.
- *See Steps 6-11.*
 - Run application.
 - If error message on SYNC display screen or no activity after 10 minutes.
 - See TSB [22-2404](#) - Module Recovery.
 - Retry TCU software update with same USB drive.
- NEW !** 14. Select **APIM** - Accessory Protocol Interface Module (APIM/SYNC) - software update.
- *See Steps 6-11.*
 - Run application.
 - Follow General Service Bulletin (GSB) 21-7088 - SYNC Programming, USB flash drive method.
 - If error message on SYNC display screen or no activity after 10 minutes.
 - See TSB [22-2404](#) - Module Recovery.
 - Retry APIM software update with same USB drive.

NOTE: Step 15 is a required step separate from Step **12**. Please follow all steps exactly as written.

- NEW !** 15. Select **GWM** - Gateway Module (GWM) - software update.
- *See Steps 6-11.*
 - Run application.
- NEW !** 16. *Read the Gateway Module (GWM) Configuration Data Application.*
- *Run application.*
- NEW !** 17. Select **IPMA** – Image Processing Module A (IPMA) - software update.
- *See Steps 6-11.*
 - Run application
 - Coordinated update of four modules.
 - Select **OK** if conditions are met to continue to next module including; Camera Module Rear (CMR), then Cruise Control Module (CCM) module, and then the Power Steering Control Module (PSCM).
 - Refer to TSB's [22-2121](#) and [22-2295](#).
- NEW !** 18. Select **APIM** - Accessory Protocol Interface Module (APIM)/**TCU - Telematics Control Unit (TCU)** - software update.
- *See Steps 6-11.*
 - Run application.
 - If no update is available, move to the next module in the sequence.
- NEW !** 19. Select **GWM** - Gateway Module (GWM) - software update.
- *See Steps 6-11.*
 - Run application.
 - If no update is available, move to the next module in the sequence.
- NEW !** 20. *Select **APIM** - Accessory Protocol Interface Module (APIM/SYNC) - software update.*
- *See Steps 6-11.*
 - *Run application.*
 - *If no update is available, move to the next module in the sequence.*



NEW ! NOTE: If IPC software update is not offered in the sequence, check for APIM/SYNC software update and **Run the application**. Re-check for IPC update once APIM/SYNC update completes.

NEW ! 21. Select **IPC - Instrument Panel Cluster (IPC)** - software update.

- See Steps 6-11.
- Run application.
 - If IPC module fails to update over USB, FDRS should ask "Did the update install successfully?", select **"NO"**.

NOTE: If software is at the latest level, "Run Application" will not be available.

- Follow FDRS prompts and select: "Try CAN programming process".
Reprogram time takes approximately 5 hours using VCM3 (program time is significantly longer with VCM2).
- No tech interaction is needed once programming has started.

NOTE: If software is at the latest level, "Run Application" will not be available.

- Verify that an Over The Air (OTA) update was previously installed.
- Log into Professional Technician System (PTS) > Connected Vehicle tab > OTA Dashboard.
Click on **Release Notes** to confirm what was included in the OTA update.
- If "Campaign Successful" – continue to the next step.
- If "Failed" or "Canceled" - Refer to "If IPC module fails to update" above. See Figures 4 and 5.

NOTE: Mach-E shown, F-150 similar.

The screenshot shows the 'Over The Air Update Dashboard' for a 2021 Mustang Mach-E. The vehicle's VIN is 3FMTK4SXMME01910. The latest status is 'Campaign Successful', dated February 10, 2022, at 04:31 PM, with update ID 488616-515632. Below the status, there are two tables. The first table, 'Over The Air Updates Currently In Process', is empty and displays 'No OTA Currently In Process'. The second table, 'Over The Air Update 60 Days History', contains one entry with the following details:

Update ID	Deployment ID	Date	Time	Module	Completion Status	Error Message	Update Status	Vehicle Inhibit	Wi-Fi Required	Release Notes
488616-515632	99c4939c-dcb0-4226-a026-af8cd6c2f1ab	February 10, 2022	04:31 PM	GWM	Campaign Successful		S1010	No	No	Release Notes

FIGURE 4






FIGURE 5

22. Mach-E vehicles **ONLY. Not required for F-150.**

- Does FSA 21P22 need to be performed?
YES - Perform FSA 21P22 then proceed to Step 22.
NO - Proceed to Step 22.

NEW ! 23. Select **GWM** - Gateway Module (GWM) - software update.

- See Steps 6-11.
- Run application.
- If no update is available, move to the next module in the sequence.

NEW ! 24. Select **APIM** - Accessory Protocol Interface Module (APIM / SYNC) - software update.

- See Steps 6-11.
- Run application.
- If no update is available, move to the next Step.

25. Mach-E vehicles **ONLY. Not required for F-150.**

- Select Toolbox tab in FDRS.
- Perform two (2) hard resets from FDRS main menu to reset SYNC (Otherwise hands free option will not be visible).
- Select **APIM** – Reset the SYNC module [APIM] / **Download** and **Run**.

26. F-150 vehicles.

- Select Toolbox tab in FDRS.
- Perform a hard reset from FDRS main menu to reset SYNC (otherwise hands-free option will not be visible).
- Select **APIM** – Reset the SYNC module [APIM] / **Download** and **Run**.

NOTE: Technical information continued on the following page.



NOTE: Program appropriate vehicle modules before performing diagnostics and clear all DTCs after programming. For DTCs generated after programming, follow normal diagnostic service procedures.

NEW ! 27. Testing BlueCruise to confirm installation (BlueCruise test drive over 0.5 hours is optional *but recommended to confirm operation*).

NOTE: There are both Hands-ON and Hands-FREE driving assist modes. Both functions are enabled by turning on "Lane Centering Assist with Hands-Free."

28. Turn ON: **Adaptive Cruise Control, Lane Centering with Hands-Free, and Activation Prompts.** See Figure 6.

NOTE: F-150 shown, Mach-E similar. Touch **Settings** on vehicle's SYNC screen > Tap **Driver Assistance** > Select **Cruise Control** > Press **Lane Centering with Hands-Free** > Touch **Activation Prompts**.




FIGURE 6



NEW !

- **Confirm BlueCruise Subscription:** Go to SYNC and selecting General, then Settings, then About SYNC. Ensure the “Hands-Free Driving Mode available” shows a date in the future.
 - See Figure 7 below for Mach-E, F-150 similar.
 - **Date structure listed as Day – Month – Year.**
 - Figure 6 example shows an expiration date of March 14, 2022 which is past.
 - If the expiration date has past, the GWM has not been fully updated, **return to Step 12.**
- Determine the nearest hands-free Blue Zone roadway entry ramp locations near your Dealership.
 - See attachment IV - **which now includes a route finding map link as an option.**
 - GPS Coordinates can be used with online mapping to provide directions from dealer. Ranked per closest entry point.
 - Some dealers may not have a Blue Zone within a reasonable distance but can still test the Hands-On function.
 - The Hands-On BlueCruise function can still be tested on any open highway with clearly defined lane markings with a vehicle speed above 40 mph (64kmh).
- If test drive can be completed within the allocated Labor Time of 0.5 Hours, perform test drive.

NOTE: Technical information continued on the following page.




FIGURE 7



NEW ! *NOTE: If "Intelligent Cruise Control" is shown under the Cruise Control menu – The BlueCruise programing is NOT complete. Return to step 1. See Figure 8.*

NOTE: F-150 shown, Mach-E similar.




FIGURE 8

29. Use the steering wheel button to turn ON Lane Keep Assist. See Figure 9.



FIGURE 9



NEW ! 30. To verify "Hands-ON" drive assist, press the cruise control steering wheel button to activate when the following conditions are satisfied. See Figure 10.

- Settings from previous steps are verified.
- All Vehicle cameras are clean.
- Drive above 40 mph (64.37 kph).
- Drive on a road surface with well-marked lane lines.
- The same conditions are needed for Hands-OFF drive assist.




FIGURE 10

NOTE: Cluster view when "Hands-ON" drive assist is functional. See Figure 11.




FIGURE 11



NEW ! 31. Optional if performing Hands-OFF BlueCruise test drive. See Figure 12.

- All previous parameters and settings are met.
- Driving in confirmed Blue Zone.
- Activate cruise control from the steering wheel button.
- A blue cluster screen and "Hands-Free" icon present indicates full BlueCruise functionality.

NOTE: F-150 shown, Mach-E similar.




FIGURE 12



Important Information for Module Programming

NOTE: When programming a module, use the following basic checks to ensure programming completes without errors.

- Make sure the 12V battery is fully charged before carrying out the programming steps.
- Connect FDRS/scan tool to a power source.

NOTE: A good internet connection is necessary to identify the vehicle and to load the diagnostic software.

- Inspect VCM/VCMM and cables for any damage. Make sure scan tool connections are not interrupted during programming.
- A hardwired connection is strongly recommended.
- Turn off all unnecessary accessories (radio, heated/cooled seats, headlamps, interior lamps, HVAC system, etc.) and close doors.
- Disconnect/depower any aftermarket accessories (remote start, alarm, power inverter, CB radio, etc.).
- Follow all scan tool on-screen instructions carefully.
- Disable FDRS/scan tool sleep mode, screensaver, hibernation modes.
- Create all sessions key-on-engine-off (KOEO). Starting the vehicle before creating a session will cause errors within the programming inhale process.

Recovering a module when programming has resulted in a blank module

- a. Disconnect the VCMII or VCMM from the data link connector (DLC) and your PC.
- b. After ten seconds, reconnect the VCMII/VCMM to the DLC and the PC. Launch FDRS. The VCMII/VCMM icon should turn green in the bottom right corner of the screen. If it does not, troubleshoot the FDRS to VCM connection.
- c. If you are using the same FDRS as the initial programming attempt, select the appropriate VIN from the Vehicle Identification menu. If you are using a different FDRS, select "Read VIN from Vehicle" and proceed through the Network Test.
- d. In the Toolbox menu, navigate to the failed module and Download/Run Programmable Module Installation (PMI). Follow the on-screen prompts. When asked if the original module is installed, select "No" and continue through the installation application.
- e. Once programming has completed, a screen may list additional steps required to complete the programming process. Make sure all applicable steps are followed in order.

