TSB 08-066-24 (REV 02) (JUL 17)
Model: 2015 Cayenne S E-Hybrid
Warm Weather Water Intrusion Front Door Glass Wipe / Grizzly Remover, 2 MPN 95 MPN 2/3 Front Grill Seals - Right Or Or

Date: 11-21-24

Model: 2015 Cayenne S E-Hybrid

Warm Weather Water Intrusion Front Door Glass Wipe / Grizzly Remover, 2 MPN 95 MPN 2/3 Front Grill Seals - Right Or Or

Issue

Customer may report water intrusion into the front door area. Water may be observed on the floor mat in the area of the front door or on the door panel.

Cause

Water intrusion into the front door area may be caused by the rubber wipe strip, the door panel, or the door seal.

Correction

Remove the rubber wipe strip, the door panel, or the door seal and replace with the new part. Apply the rubber wipe strip and the door seal using the new Grizzly remover. Install the door panel using the new Grizzly remover. Apply the new Grizzly remover to the rubber wipe strip, the door panel, and the door seal