

Last Vehicle Status Update: May 07, 2024 02:58 PM

\*Note: Do not use as a pressure gauge

Refresh

### Odometer



83446 Miles

### High Voltage Battery



Battery State of Charge : 71%

Battery Range : 180 Miles

### Tire Pressure (PSI)\*



Recommended Tire Pressure(cold)

Front : 39 | Rear : 39

Last Vehicle Health Update: May 01, 2024 02:26 PM

March 2024

| Sun | Mon | Tue | Wed | Thu |
|-----|-----|-----|-----|-----|
|     |     |     |     |     |
| 3   | 4   | 5   | 6   | 7   |
| 10  | 11  | 12  | 13  | 14  |
| 17  | 18  | 19  | 20  | 21  |
| 24  | 25  | 26  | 27  | 28  |
| 31  |     |     |     |     |

April 2024

| Sun | Mon | Tue | Wed | Thu |
|-----|-----|-----|-----|-----|
|     | 1   | 2   | 3   | 4   |
| 7   | 8   | 9   | 10  | 11  |
| 14  | 15  | 16  | 17  | 18  |
| 21  | 22  | 23  | 24  | 25  |
| 28  | 29  | 30  |     |     |

May 2024

| Sun | Mon | Tue | Wed | Thu |
|-----|-----|-----|-----|-----|
|     |     |     | 1   | 2   |
| 5   | 6   | 7   | 8   | 9   |
| 12  | 13  | 14  | 15  | 16  |
| 19  | 20  | 21  | 22  | 23  |
| 26  | 27  | 28  | 29  | 30  |

Vehicle Health Alerts (VHA) and Diagnostic Trouble Codes (DTC)

Date | Time | Odometer

Event Description



Module

DTC

: FT : SB

TSB/GSB/SSM



Send to Search

Description

May 01, 2024

Time : 02:26 PM

Odometer :  
83445 mi

|      |  |                 |           |
|------|--|-----------------|-----------|
| CMR  |  | B15E1 : 97 : 0C | SSM       |
| PSCM |  | U2016 : 47 : 48 |           |
| PSCM |  | U3000 : 49 : 48 | TSB / SSM |
| CMR  |  | B15E2 : 97 : 0C | SSM       |
| CCM  |  | C1A67 : 97 : 28 | GSB       |
| CMR  |  | B115E : 97 : 0C | SSM       |

Select All

- Driver Side LED
- Control Module Main Software
- Control Module
- Passenger Side LED
- Forward Looking Sensor
- Camera Module

April 08, 2024

Time : 01:34 PM

Odometer :  
83444 mi

|       |  |                 |           |
|-------|--|-----------------|-----------|
| ★ CMR |  | B115E : 97 : 0C | SSM       |
| ★ CMR |  | B15E2 : 97 : 0C | SSM       |
| ★ CMR |  | B15E1 : 97 : 0C | SSM       |
| CCM   |  | C1A67 : 97 : 28 | GSB       |
| PSCM  |  | U2016 : 47 : 48 |           |
| PSCM  |  | U3000 : 49 : 48 | TSB / SSM |

Select All

- Camera Module
- Passenger Side LED
- Driver Side LED
- Forward Looking Sensor
- Control Module Main Software
- Control Module

Time : 03:19 PM

Odometer :  
83358 mi



Clear Alert -  
Collision Assist  
Unavailable

|       |  |                |           |
|-------|--|----------------|-----------|
| BECMB |  | B1142: 62 : 08 |           |
| CMR   |  | B15E1: 97 : 08 | SSM       |
| CMR   |  | B15E2: 97 : 08 | SSM       |
| PSCM  |  | U2016: 47 : 48 |           |
| PSCM  |  | U3000: 49 : 48 | TSB / SSM |
| CCM   |  | C1A67: 97 : 28 | GSB       |
| CMR   |  | B115E: 97 : 08 | SSM       |

- Ignition Status 1
- Driver Side LED
- Passenger Side LED
- Control Module Main Software
- Control Module
- Forward Looking Sensor
- Camera Module

Time : 02:53 PM

Odometer :  
83337 mi



New Alert - [Show Details](#)  
Collision Assist  
Unavailable

|       |  |                |           |
|-------|--|----------------|-----------|
| BECMB |  | B1142: 62 : 08 |           |
| CMR   |  | B15E1: 97 : 08 | SSM       |
| CMR   |  | B15E2: 97 : 08 | SSM       |
| PSCM  |  | U2016: 47 : 48 |           |
| PSCM  |  | U3000: 49 : 48 | TSB / SSM |
| CCM   |  | C1A67: 97 : 28 | GSB       |
| CMR   |  | B115E: 97 : 08 | SSM       |

- Ignition Status 1
- Driver Side LED
- Passenger Side LED
- Control Module Main Software
- Control Module
- Forward Looking Sensor
- Camera Module

Time : 11:26 AM

Odometer :  
83331 mi



Clear Alert -  
Collision Assist  
Unavailable

|       |  |                |           |
|-------|--|----------------|-----------|
| BECMB |  | B1142: 62 : 08 |           |
| CMR   |  | B15E1: 97 : 08 | SSM       |
| CMR   |  | B15E2: 97 : 08 | SSM       |
| PSCM  |  | U2016: 47 : 48 |           |
| PSCM  |  | U3000: 49 : 48 | TSB / SSM |
| CCM   |  | C1A67: 97 : 28 | GSB       |
| CMR   |  | B115E: 97 : 08 | SSM       |

- Ignition Status 1
- Driver Side LED
- Passenger Side LED
- Control Module Main Software
- Control Module
- Forward Looking Sensor
- Camera Module

Time : 08:00 AM

Odometer :  
83320 mi



New Alert - [Show Details](#)  
Collision Assist  
Unavailable

|       |  |                |           |
|-------|--|----------------|-----------|
| BECMB |  | B1142: 62 : 08 |           |
| CMR   |  | B15E1: 97 : 08 | SSM       |
| CMR   |  | B15E2: 97 : 08 | SSM       |
| PSCM  |  | U2016: 47 : 48 |           |
| PSCM  |  | U3000: 49 : 48 | TSB / SSM |
| CCM   |  | C1A67: 97 : 28 | GSB       |
| CMR   |  | B115E: 97 : 08 | SSM       |

- Ignition Status 1
- Driver Side LED
- Passenger Side LED
- Control Module Main Software
- Control Module
- Forward Looking Sensor
- Camera Module

Time : 06:54 AM

Odometer :  
83271 mi

|         |  |                |     |
|---------|--|----------------|-----|
| ★ BECMB |  | B1142: 62 : 08 |     |
| ★ CCM   |  | C1A67: 97 : 28 | GSB |

- Ignition Status 1
- Forward Looking Sensor

★ CMR | B15E2: 97 : 08 SSM  
CMR | B15E1: 97 : 08 SSM  
CMR | B115E: 97 : 08 SSM  
PSCM | U2016: 47 : 48  
PSCM | U3000: 49 : 48 TSB / SSM

⚠ Passenger Side LED  
 ⚠ Driver Side LED  
 ⚠ Camera Module  
 ⚠ Control Module Main Software  
 ⚠ Control Module

Time : 12:08 AM



OTA On-Vehicle  
Activity-Update  
Activation is  
finished

Time : 12:04 AM



OTA On-Vehicle  
Activity-Vehicle  
Activation Start

Time : 04:28 PM

Odometer :  
83069 mi



Clear Alert -  
Collision Assist  
Unavailable

|        |  |                |           |
|--------|--|----------------|-----------|
| CMR    |  | B15E1: 97 : 08 | SSM       |
| CCM    |  | C1A67: 97 : AF | GSB       |
| SOBDMB |  | P060C: 47 : 28 |           |
| GFM    |  | U0100: 00 : 08 | TSB / TSB |
| PSCM   |  | U2016: 47 : 48 |           |
| SOBDMB |  | P06A7: 00 : 28 |           |
| SOBDMB |  | U0111: 00 : 28 |           |
| PSCM   |  | U3000: 49 : 48 | TSB / SSM |
| CMR    |  | B15E2: 97 : 0E | SSM       |
| SOBDMB |  | P0887: 00 : 28 |           |
| GFM    |  | U0293: 00 : 08 | TSB / TSB |
| CMR    |  | B115E: 97 : 08 | SSM       |

- Driver Side LED
- Forward Looking Sensor
- Internal Control Module Main Processor Performance
- Lost Communication With ECM/PCM 'A'
- Control Module Main Software
- Sensor Reference Voltage 'B' Circuit Range/Performance
- Lost Communication With Battery Energy Control Module 'A'
- Control Module
- Passenger Side LED
- TCM Power Relay Control Circuit High
- Lost Communication With Hybrid/EV Powertrain Control Module 'A'
- Camera Module

Time : 03:12 PM

Odometer :  
83062 mi



New Alert -  
Collision Assist  
Unavailable

[Show Details](#)

|        |  |                |           |
|--------|--|----------------|-----------|
| CMR    |  | B15E1: 97 : 08 | SSM       |
| CCM    |  | C1A67: 97 : AF | GSB       |
| SOBDMB |  | P060C: 47 : 28 |           |
| GFM    |  | U0100: 00 : 08 | TSB / TSB |
| PSCM   |  | U2016: 47 : 48 |           |
| SOBDMB |  | P06A7: 00 : 28 |           |
| SOBDMB |  | U0111: 00 : 28 |           |
| PSCM   |  | U3000: 49 : 48 | TSB / SSM |
| CMR    |  | B15E2: 97 : 0E | SSM       |
| SOBDMB |  | P0887: 00 : 28 |           |
| GFM    |  | U0293: 00 : 08 | TSB / TSB |
| CMR    |  | B115E: 97 : 08 | SSM       |

- Driver Side LED
- Forward Looking Sensor
- Internal Control Module Main Processor Performance
- Lost Communication With ECM/PCM 'A'
- Control Module Main Software
- Sensor Reference Voltage 'B' Circuit Range/Performance
- Lost Communication With Battery Energy Control Module 'A'
- Control Module
- Passenger Side LED
- TCM Power Relay Control Circuit High
- Lost Communication With Hybrid/EV Powertrain Control Module 'A'
- Camera Module

Time : 01:10 PM

Odometer :  
83057 mi










Clear Alert -  
Collision Assist  
Unavailable

|        |  |                |           |
|--------|--|----------------|-----------|
| CMR    |  | B15E1: 97 : 08 | SSM       |
| CCM    |  | C1A67: 97 : AF | GSB       |
| SOBDMB |  | P060C: 47 : 28 |           |
| GFM    |  | U0100: 00 : 08 | TSB / TSB |

- Driver Side LED
- Forward Looking Sensor
- Internal Control Module Main Processor Performance
- Lost Communication With ECM/PCM 'A'

|        |  |                |           |
|--------|--|----------------|-----------|
| PSCM   |  | U2016: 47 : 48 |           |
| SOBDMB |  | P06A7: 00 : 28 |           |
| SOBDMB |  | U0111: 00 : 28 |           |
| PSCM   |  | U3000: 49 : 48 | TSB / SSM |
| CMR    |  | B15E2: 97 : 0E | SSM       |
| SOBDMB |  | P0887: 00 : 28 |           |
| GFM    |  | U0293: 00 : 08 | TSB / TSB |
| CMR    |  | B115E: 97 : 08 | SSM       |


-  Control Module Main Software
-  Sensor Reference Voltage 'B' Circuit Range/Performance
-  Lost Communication With Battery Energy Control Module 'A'
-  Control Module
-  Passenger Side LED
-  TCM Power Relay Control Circuit High
-  Lost Communication With Hybrid/EV Powertrain Control Module 'A'
-  Camera Module













Time : 12:38 PM  
Odometer :  
83048 mi



New Alert -  
Collision Assist  
Unavailable

[Show  
Details](#)

|   |        |  |  |           |
|---|--------|--|--|-----------|
| ★ | CCM    |  |  C1A67: 97 : AF | GSB       |
| ★ | CMR    |  | B115E: 97 : 08   | SSM       |
| ★ | CMR    |  | B15E2: 97 : 0E   | SSM       |
| ★ | CMR    |  | B15E1: 97 : 08   | SSM       |
| ★ | GFM    |  | U0293: 00 : 08   | TSB / TSB |
| ★ | GFM    |  | U0100: 00 : 08   | TSB / TSB |
| ★ | SOBDMB |  | P0887: 00 : 28   |           |
| ★ | SOBDMB |  | U0111: 00 : 28   |           |
| ★ | SOBDMB |  | P06A7: 00 : 28   |           |
| ★ | SOBDMB |  | P060C: 47 : 28   |           |
|   | PSCM   |  | U2016: 47 : 48   |           |
|   | PSCM   |  | U3000: 49 : 48   | TSB / SSM |

-  Forward Looking Sensor
-  Camera Module
-  Passenger Side LED
-  Driver Side LED
-  Lost Communication With Hybrid/EV Powertrain Control Module 'A'
-  Lost Communication With ECM/PCM 'A'
-  TCM Power Relay Control Circuit High
-  Lost Communication With Battery Energy Control Module 'A'
-  Sensor Reference Voltage 'B' Circuit Range/Performance
-  Internal Control Module Main Processor Performance
-  Control Module Main Software
-  Control Module

March 21, 2024

Select All

Time : 11:43 AM

Odometer :  
82911 mi

|   |        |  |                |           |
|---|--------|--|----------------|-----------|
| ★ | CMR    |  | B115E: 97 : 0C | SSM       |
| ★ | CMR    |  | B15E2: 97 : 0C | SSM       |
| ★ | CMR    |  | B15E1: 97 : 0C | SSM       |
| ★ | GFM    |  | U0293: 00 : 0A | TSB / TSB |
| ★ | GFM    |  | U0100: 00 : 0A | TSB / TSB |
| ★ | SOBDMB |  | P060C: 47 : AF |           |
| ★ | SOBDMB |  | P0887: 00 : 2F |           |
| ★ | SOBDMB |  | U0111: 00 : AE |           |
| ★ | SOBDMB |  | P06A7: 00 : AF |           |
|   | PSCM   |  | U2016: 47 : 48 |           |
|   | PSCM   |  | U3000: 49 : 48 | TSB / SSM |

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Lost Communication With Hybrid/EV Powertrain Control Module 'A'
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Internal Control Module Main Processor Performance
- ⚠ TCM Power Relay Control Circuit High
- ⚠ Lost Communication With Battery Energy Control Module 'A'
- ⚠ Sensor Reference Voltage 'B' Circuit Range/Performance
- ⚠ Control Module Main Software
- ⚠ Control Module

March 19, 2024

Select All

Time : 02:30 PM

Odometer :  
82791 mi

|   |      |  |                |           |
|---|------|--|----------------|-----------|
| ★ | CMR  |  | B115E: 97 : 08 | SSM       |
| ★ | CMR  |  | B15E2: 97 : 08 | SSM       |
| ★ | CMR  |  | B15E1: 97 : 08 | SSM       |
|   | GFM  |  | U0100: 00 : 08 | TSB / TSB |
|   | GFM  |  | U0293: 00 : 08 | TSB / TSB |
|   | PSCM |  | U2016: 47 : 48 |           |
|   | PSCM |  | U3000: 49 : 48 | TSB / SSM |

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With Hybrid/EV Powertrain Control Module 'A'
- ⚠ Control Module Main Software
- ⚠ Control Module

March 15, 2024

Select All

Time : 05:50 PM

Odometer :  
82700 mi

|   |      |  |                |           |
|---|------|--|----------------|-----------|
| ★ | CMR  |  | B115E: 97 : 0C | SSM       |
| ★ | CMR  |  | B15E2: 97 : 0C | SSM       |
| ★ | CMR  |  | B15E1: 97 : 0C | SSM       |
| ★ | GFM  |  | U0293: 00 : 08 | TSB / TSB |
| ★ | GFM  |  | U0100: 00 : 08 | TSB / TSB |
|   | IPMA |  | B115E: 31 : 28 |           |
|   | PSCM |  | U2016: 47 : 48 |           |
|   | PSCM |  | U3000: 49 : 48 | TSB / SSM |

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Lost Communication With Hybrid/EV Powertrain Control Module 'A'
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Camera Module
- ⚠ Control Module Main Software
- ⚠ Control Module

March 13, 2024

Select All

Time : 05:19 PM

Odometer :  
82572 mi

|   |      |  |                |           |
|---|------|--|----------------|-----------|
| ★ | CMR  |  | B115E: 97 : 08 | SSM       |
| ★ | CMR  |  | B15E2: 97 : 08 | SSM       |
| ★ | CMR  |  | B15E1: 97 : 08 | SSM       |
| ★ | GFM  |  | U0293: 00 : 0A | TSB / TSB |
| ★ | GFM  |  | U0100: 00 : 0A | TSB / TSB |
|   | CCM  |  | C1A67: 97 : 28 | GSB       |
|   | IPMA |  | B115E: 31 : 28 |           |
|   | PSCM |  | U2016: 47 : 48 |           |
|   | PSCM |  | U3000: 49 : 48 | TSB / SSM |

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Lost Communication With Hybrid/EV Powertrain Control Module 'A'
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Forward Looking Sensor
- ⚠ Camera Module
- ⚠ Control Module Main Software
- ⚠ Control Module

Time : 05:05 PM

Odometer :  
82564 mi

|   |      |  |                |           |
|---|------|--|----------------|-----------|
| ★ | CMR  |  | B115E: 97 : 0C | SSM       |
| ★ | CMR  |  | B15E2: 97 : 0C | SSM       |
| ★ | CMR  |  | B15E1: 97 : 0C | SSM       |
|   | ABS  |  | U023A: 00 : 28 |           |
|   | CCM  |  | U2008: 08 : 28 |           |
|   | CCM  |  | C1A67: 97 : 28 | GSB       |
|   | GFM  |  | U0100: 00 : 08 | TSB / TSB |
|   | GFM  |  | U0293: 00 : 08 | TSB / TSB |
|   | IPMA |  | B115E: 31 : 28 |           |
|   | PSCM |  | U2016: 47 : 48 |           |
|   | PSCM |  | U3000: 49 : 48 | TSB / SSM |

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Lost Communication With Image Processing Module A
- ⚠ Sensor Cluster
- ⚠ Forward Looking Sensor
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With Hybrid/EV Powertrain Control Module 'A'
- ⚠ Camera Module
- ⚠ Control Module Main Software
- ⚠ Control Module

Time : 12:51 PM

Odometer :  
82506 mi

|  |      |  |                |           |
|--|------|--|----------------|-----------|
|  | CMR  |  | B15E1: 97 : 08 | SSM       |
|  | IPMA |  | B115E: 31 : 28 |           |
|  | CMR  |  | B15E2: 97 : 08 | SSM       |
|  | ABS  |  | U023A: 00 : 28 |           |
|  | GFM  |  | U0100: 00 : 08 | TSB / TSB |
|  | PSCM |  | U2016: 47 : 48 |           |
|  | CCM  |  | U2008: 08 : 28 |           |
|  | PSCM |  | U3000: 49 : 48 | TSB / SSM |
|  | CCM  |  | C1A67: 97 : 28 | GSB       |
|  | GFM  |  | U0293: 00 : 08 | TSB / TSB |
|  | CMR  |  | B115E: 97 : 08 | SSM       |
|  | GFM  |  | U0100: 00 : 0A | TSB / TSB |
|  | GFM  |  | U0293: 00 : 0A | TSB / TSB |











- ⚠ Driver Side LED
- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Lost Communication With Image Processing Module A
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Control Module Main Software
- ⚠ Sensor Cluster
- ⚠ Control Module
- ⚠ Forward Looking Sensor
- ⚠ Lost Communication With Hybrid/EV Powertrain Control Module 'A'
- ⚠ Camera Module
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With Hybrid/EV Powertrain Control Module 'A'

Time : 06:58 AM

Odometer :  
82447 mi















|   |     |  |                |           |
|---|-----|--|----------------|-----------|
| ★ | GFM |  | U0293: 00 : 0A | TSB / TSB |
| ★ | GFM |  | U0100: 00 : 0A | TSB / TSB |
|   | ABS |  | U023A: 00 : 28 |           |

- ⚠ Lost Communication With Hybrid/EV Powertrain Control Module 'A'
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With Image Processing Module A

|      |  |                |           |  |
|------|--|----------------|-----------|--|
| CCM  |  | U2008: 08 : 28 | GSB       | <input type="checkbox"/>  Sensor Cluster   |
| CCM  |  | C1A67: 97 : 28 | GSB       | <input type="checkbox"/>  Forward Looking Sensor  |
| CMR  |  | B15E1: 97 : 08 | SSM       | <input type="checkbox"/>  Driver Side LED  |
| CMR  |  | B15E2: 97 : 08 | SSM       | <input type="checkbox"/>  Passenger Side LED  |
| CMR  |  | B115E: 97 : 08 | SSM       | <input type="checkbox"/>  Camera Module   |
| GFM  |  | U0100: 00 : 08 | TSB / TSB | <input type="checkbox"/>  Lost Communication With ECM/PCM 'A'                             |
| GFM  |  | U0293: 00 : 08 | TSB / TSB | <input type="checkbox"/>  Lost Communication With Hybrid/EV Powertrain Control Module 'A' |
| IPMA |  | B115E: 31 : 28 |           | <input type="checkbox"/>  Camera Module   |
| PSCM |  | U2016: 47 : 48 |           | <input type="checkbox"/>  Control Module Main Software                                    |
| PSCM |  | U3000: 49 : 48 | TSB / SSM | <input type="checkbox"/>  Control Module  |

March 08, 2024

Time : 02:10 PM  
Odometer :  
82425 mi

|   |      |  |                |           |  |
|---|------|--|----------------|-----------|--|
| ★ | ABS  |  | U023A: 00 : 28 |           | <input type="checkbox"/>  Lost Communication With Image Processing Module A                 |
| ★ | CCM  |  | C1A67: 97 : 28 | GSB       | <input type="checkbox"/>  Forward Looking Sensor  |
| ★ | CCM  |  | U2008: 08 : 28 |           | <input type="checkbox"/>  Sensor Cluster  |
| ★ | CMR  |  | B115E: 97 : 0C | SSM       | <input type="checkbox"/>  Camera Module   |
| ★ | CMR  |  | B15E2: 97 : 0C | SSM       | <input type="checkbox"/>  Passenger Side LED  |
| ★ | CMR  |  | B15E1: 97 : 0C | SSM       | <input type="checkbox"/>  Driver Side LED   |
| ★ | CMR  |  | B115E: 97 : 08 | SSM       | <input type="checkbox"/>  Camera Module   |
| ★ | CMR  |  | B15E2: 97 : 08 | SSM       | <input type="checkbox"/>  Passenger Side LED  |
| ★ | CMR  |  | B15E1: 97 : 08 | SSM       | <input type="checkbox"/>  Driver Side LED  |
| ★ | GFM  |  | U0293: 00 : 08 | TSB / TSB | <input type="checkbox"/>  Lost Communication With Hybrid/EV Powertrain Control Module 'A' |
| ★ | GFM  |  | U0100: 00 : 08 | TSB / TSB | <input type="checkbox"/>  Lost Communication With ECM/PCM 'A'                             |
| ★ | IPMA |  | B115E: 31 : 28 |           | <input type="checkbox"/>  Camera Module   |
| ★ | PSCM |  | U3000: 49 : 48 | TSB / SSM | <input type="checkbox"/>  Control Module  |
| ★ | PSCM |  | U2016: 47 : 48 |           | <input type="checkbox"/>  Control Module Main Software                                    |

Select All