

Last Vehicle Status Update: April 23, 2024 06:18 PM

*Note: Do not use as a pressure gauge

Refresh

Odometer



2725 Miles

High Voltage Battery



Battery State of Charge : 84%

Battery Range : 200 Miles

Tire Pressure (PSI)*



Recommended Tire Pressure(cold)



Front : **Unknown** | Rear : **Unknown**

Last Vehicle Health Update: April 23, 2024 05:58 PM








February 2024

Sun	Mon	Tue	Wed	Thu
				1
4	5	6	7	8
11	12	13	14	15
18	19	20	21	22
25	26	27	28	29

March 2024

Sun	Mon	Tue	Wed	Thu
3	4	5	6	7
10	11	12	13	14 
17	18	19	20	21
24	25	26	27	28
31 				

April 2024

Sun	Mon	Tue	Wed	Thu
	1	2	3	4
7	8	9	10	11
14	15 	16 	17 	18  
21	22 	23 	24	25
28	29	30		

Vehicle Health Alerts (VHA) and Diagnostic Trouble Codes (DTC)

Date | Time | Odometer

Event Description



Module

DTC

FT : SB

TSB/GSB/SSM



Send to Search

Description

Time : 01:57 PM

Odometer :
2725 mi





★	PCM		P161C: 00 : 68		<input type="checkbox"/>		Automatic Engine Shutdown Mismatch with Vehicle Configuration
	BECM		P2C85: 1E : 68		<input type="checkbox"/>		Hybrid/EV Battery Voltage External Isolation Fault
	CMR		B15E1: 97 : 0C	SSM	<input type="checkbox"/>		Driver Side LED
	CMR		B15E2: 97 : 0C	SSM	<input type="checkbox"/>		Passenger Side LED
	CMR		B115E: 97 : 0C	SSM	<input type="checkbox"/>		Camera Module
	IPMA		B1578: 89 : 28		<input type="checkbox"/>		Digital Park Assist Camera Vision System
	OBCC		U3000: 16 : 68	SSM / TSB	<input type="checkbox"/>		Control Module
	OBCC		P1A3C: 00 : 68	SSM	<input type="checkbox"/>		Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
	PCM		P087F: 00 : 28		<input type="checkbox"/>		One Pedal Drive System Performance
	PCM		U0415: 00 : 28		<input type="checkbox"/>		Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
	PSCM		U0415: 00 : 48		<input type="checkbox"/>		Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
	PSCM		U0151: 00 : 08		<input type="checkbox"/>		Lost Communication With Restraints Control Module
	SOBDM		P1A3C: 00 : 28		<input type="checkbox"/>		Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
	SOBDM		P0D56: 24 : 68		<input type="checkbox"/>		Proximity Detection Circuit 'A'
	VDM		U0442: 68 : 28		<input type="checkbox"/>		Invalid Data Received From ECM/PCM 'B'

Time : 01:14 PM

Odometer :
2703 mi

★	CMR		B115E: 97 : 0C	SSM	<input type="checkbox"/>		Camera Module
★	CMR		B15E2: 97 : 0C	SSM	<input type="checkbox"/>		Passenger Side LED
★	CMR		B15E1: 97 : 0C	SSM	<input type="checkbox"/>		Driver Side LED
★	PCM		P161C: 00 : 2C		<input type="checkbox"/>		Automatic Engine Shutdown Mismatch with Vehicle Configuration
	BECM		P2C85: 1E : 68		<input type="checkbox"/>		Hybrid/EV Battery Voltage External Isolation Fault
	IPC		U0415: 00 : 08		<input type="checkbox"/>		Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
	IPMA		B1578: 89 : 28		<input type="checkbox"/>		Digital Park Assist Camera Vision System
	OBCC		U3000: 16 : 68	SSM / TSB	<input type="checkbox"/>		Control Module
	OBCC		P1A3C: 00 : 68	SSM	<input type="checkbox"/>		Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
	PCM		P087F: 00 : 28		<input type="checkbox"/>		One Pedal Drive System Performance
	PCM		U0415: 00 : 28		<input type="checkbox"/>		Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
	PSCM		U0415: 00 : 48		<input type="checkbox"/>		Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

PSCM		U0151: 00 : 08
SOBDM		P1A3C: 00 : 28
SOBDM		P0D56: 24 : 68
VDM		U0442: 68 : 28

-  Lost Communication With Restraints Control Module
-  Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
-  Proximity Detection Circuit 'A'
-  Invalid Data Received From ECM/PCM 'B'

Time : 11:38 PM

Odometer :
2703 mi

★ VDM		U0442: 68 : 28	
BECM		P2C85: 1E : 68	
CMR		B15E1: 97 : 8F	SSM
CMR		B15E2: 97 : 8F	SSM
CMR		B115E: 97 : 8F	SSM
IPC		U0415: 00 : 08	
IPMA		B1578: 89 : 28	
OBCC		U3000: 16 : 68	SSM / TSB
OBCC		P1A3C: 00 : 68	SSM
PCM		P087F: 00 : 28	
PCM		U0415: 00 : 28	
PSCM		U0415: 00 : 48	
PSCM		U0151: 00 : 08	
SOBDM		P1A3C: 00 : 28	
SOBDM		P0D56: 24 : 68	

- ⚠ Invalid Data Received From ECM/PCM 'B'
- ⚠ Hybrid/EV Battery Voltage External Isolation Fault
- ⚠ Driver Side LED
- ⚠ Passenger Side LED
- ⚠ Camera Module
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Digital Park Assist Camera Vision System
- ⚠ Control Module
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ One Pedal Drive System Performance
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Lost Communication With Restraints Control Module
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Proximity Detection Circuit 'A'

Time : 11:00 PM

Odometer :
2703 mi

★ CMR		B115E: 97 : 8F	SSM
★ CMR		B15E2: 97 : 8F	SSM
★ CMR		B15E1: 97 : 8F	SSM
★ VDM		U0442: 68 : 2C	
BECM		P2C85: 1E : 68	
IPC		U0415: 00 : 08	
IPMA		U0565: 86 : 28	TSB
IPMA		B1578: 89 : 28	
OBCC		U3000: 16 : 68	SSM / TSB
OBCC		P1A3C: 00 : 68	SSM
PCM		P087F: 00 : 28	
PCM		U0415: 00 : 28	

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Invalid Data Received From ECM/PCM 'B'
- ⚠ Hybrid/EV Battery Voltage External Isolation Fault
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Invalid Data Received From Camera Module-Rear
- ⚠ Digital Park Assist Camera Vision System
- ⚠ Control Module
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ One Pedal Drive System Performance
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

PSCM		U0415: 00 : 48
PSCM		U0151: 00 : 08
SOBDM		P1A3C: 00 : 28
SOBDM		P0D56: 24 : 68

<input type="checkbox"/>		Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
<input type="checkbox"/>		Lost Communication With Restraints Control Module
<input type="checkbox"/>		Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
<input type="checkbox"/>		Proximity Detection Circuit 'A'

Time : 11:57 AM
Odometer :
 2703 mi

★	BECM		P2C85: 1E : 68
★	SOBDM		P0D56: 24 : 68
★	SOBDM		P1A3C: 00 : 28

<input type="checkbox"/>		Hybrid/EV Battery Voltage External Isolation Fault
<input type="checkbox"/>		Proximity Detection Circuit 'A'
<input type="checkbox"/>		Hybrid/EV Battery Charging Disabled - DC Charging Station Performance

ABS		U0253: 00 : 28	TSB
-----	--	----------------	-----

<input type="checkbox"/>		Lost Communication With Accessory Protocol Interface Module
--------------------------	--	---

CMR		B15E1: 97 : 0E	SSM
-----	--	----------------	-----

<input type="checkbox"/>		Driver Side LED
--------------------------	--	-----------------

CMR		B15E2: 97 : 0E	SSM
-----	--	----------------	-----

<input type="checkbox"/>		Passenger Side LED
--------------------------	--	--------------------

CMR		B115E: 97 : 0E	SSM
-----	--	----------------	-----

<input type="checkbox"/>		Camera Module
--------------------------	--	---------------

IPC		U0415: 00 : 08
-----	--	----------------

<input type="checkbox"/>		Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
--------------------------	--	--

IPMA		U0565: 86 : 28	TSB
------	--	----------------	-----

<input type="checkbox"/>		Invalid Data Received From Camera Module-Rear
--------------------------	--	---

IPMA		B1578: 89 : 28
------	--	----------------

<input type="checkbox"/>		Digital Park Assist Camera Vision System
--------------------------	--	--

OBCC		U3000: 16 : 68	SSM / TSB
------	--	----------------	-----------

<input type="checkbox"/>		Control Module
--------------------------	--	----------------

OBCC		P1A3C: 00 : 68	SSM
------	--	----------------	-----

<input type="checkbox"/>		Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
--------------------------	--	---

PCM		P087F: 00 : 28
-----	--	----------------

<input type="checkbox"/>		One Pedal Drive System Performance
--------------------------	--	------------------------------------

PCM		U0415: 00 : 28
-----	--	----------------

<input type="checkbox"/>		Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
--------------------------	--	--

PSCM		U0415: 00 : 48
------	--	----------------

<input type="checkbox"/>		Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
--------------------------	--	--

PSCM		U0151: 00 : 08
------	--	----------------

<input type="checkbox"/>		Lost Communication With Restraints Control Module
--------------------------	--	---

VDM		U0442: 68 : 28
-----	--	----------------

<input type="checkbox"/>		Invalid Data Received From ECM/PCM 'B'
--------------------------	--	--

Time : 11:14 PM

Odometer :
2607 mi

★	BECM		P2C85: 1E : 28	
★	CMR		B115E: 97 : 0E	SSM
★	CMR		B15E2: 97 : 0E	SSM
★	CMR		B15E1: 97 : 0E	SSM
★	IPMA		B1578: 89 : 28	
★	SOBDM		P0D56: 24 : 28	
★	SOBDM		P1A3C: 00 : 2A	
	ABS		U0253: 00 : 28	TSB
	IPC		U0415: 00 : 08	
	IPMA		U0501: 86 : 28	
	IPMA		U0565: 86 : 28	TSB
	IPMA		U049A: 86 : 28	
	OBCC		U3000: 16 : 68	SSM / TSB
	OBCC		P1A3C: 00 : 68	SSM
	PCM		P087F: 00 : 28	
	PCM		U0415: 00 : 28	
	PSCM		U0415: 00 : 48	
	PSCM		U0151: 00 : 08	
	VDM		U0442: 68 : 28	

- ⚠ Hybrid/EV Battery Voltage External Isolation Fault
- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Digital Park Assist Camera Vision System
- ⚠ Proximity Detection Circuit 'A'
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Invalid Data Received From Door Control Module 'B'
- ⚠ Invalid Data Received From Camera Module-Rear
- ⚠ Invalid Data Received From 'Door Control Module A' Control Module
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ One Pedal Drive System Performance
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Lost Communication With Restraints Control Module
- ⚠ Invalid Data Received From ECM/PCM 'B'

Time : 03:36 PM



OTA On-Vehicle
Activity-Update
Activation is
finished

Time : 03:33 PM



OTA On-Vehicle
Activity-Vehicle
Activation Start

Time : 03:32 PM



OTA On-Vehicle
Activity-Vehicle
Activation Start

Time : 01:10 PM

Odometer :

2157 mi

★	CMR		B15E1: 97 : 08	SSM	<input type="checkbox"/>	⚠	Driver Side LED
★	CMR		B115E: 97 : 08	SSM	<input type="checkbox"/>	⚠	Camera Module
★	CMR		B15E2: 97 : 08	SSM	<input type="checkbox"/>	⚠	Passenger Side LED
★	IPMA		B1578: 89 : 2E		<input type="checkbox"/>	⚠	Digital Park Assist Camera Vision System
	ABS		U0253: 00 : 28	TSB	<input type="checkbox"/>	⚠	Lost Communication With Accessory Protocol Interface Module
	BECM		P2C85: 1E : 6C		<input type="checkbox"/>	⚠	Hybrid/EV Battery Voltage External Isolation Fault
	IPC		U0415: 00 : 08		<input type="checkbox"/>	⚠	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
	IPMA		U049A: 86 : 28		<input type="checkbox"/>	⚠	Invalid Data Received From 'Door Control Module A'
	IPMA		U0501: 86 : 28		<input type="checkbox"/>	⚠	Invalid Data Received From Door Control Module 'B'
	IPMA		B115E: 31 : 28		<input type="checkbox"/>	⚠	Camera Module
	IPMA		U0565: 86 : 28	TSB	<input type="checkbox"/>	⚠	Invalid Data Received From Camera Module-Rear
	OBCC		U3000: 16 : 68	SSM / TSB	<input type="checkbox"/>	⚠	Control Module
	OBCC		P1A3C: 00 : 68	SSM	<input type="checkbox"/>	⚠	Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
	PCM		P087F: 00 : 28		<input type="checkbox"/>	⚠	One Pedal Drive System Performance
	PCM		U0415: 00 : 28		<input type="checkbox"/>	⚠	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
	PSCM		U0415: 00 : 48		<input type="checkbox"/>	⚠	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
	PSCM		U0151: 00 : 08		<input type="checkbox"/>	⚠	Lost Communication With Restraints Control Module
	SOBDM		P0D56: 24 : 68		<input type="checkbox"/>	⚠	Proximity Detection Circuit 'A'
	VDM		U0442: 68 : 28		<input type="checkbox"/>	⚠	Invalid Data Received From ECM/PCM 'B'

Time : 08:49 AM

Odometer :
1192 mi

★	CMR		B115E: 97 : 8F	SSM	<input type="checkbox"/> ⚠ Camera Module
★	CMR		B15E2: 97 : 0E	SSM	<input type="checkbox"/> ⚠ Passenger Side LED
★	CMR		B15E1: 97 : 8F	SSM	<input type="checkbox"/> ⚠ Driver Side LED
	ABS		U0253: 00 : 28	TSB	<input type="checkbox"/> ⚠ Lost Communication With Accessory Protocol Interface Module
	BECM		P2C85: 1E : 6C		<input type="checkbox"/> ⚠ Hybrid/EV Battery Voltage External Isolation Fault
	IPC		U0415: 00 : 08		<input type="checkbox"/> ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
	IPMA		U0501: 86 : 28		<input type="checkbox"/> ⚠ Invalid Data Received From Door Control Module 'B'
	IPMA		B115E: 31 : 28		<input type="checkbox"/> ⚠ Camera Module
	IPMA		U0565: 86 : 28	TSB	<input type="checkbox"/> ⚠ Invalid Data Received From Camera Module-Rear
	IPMA		U049A: 86 : 28		<input type="checkbox"/> ⚠ Invalid Data Received From 'Door Control Module A'
	OBCC		U3000: 16 : 68	SSM / TSB	<input type="checkbox"/> ⚠ Control Module
	OBCC		P1A3C: 00 : 68	SSM	<input type="checkbox"/> ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
	PCM		P087F: 00 : 28		<input type="checkbox"/> ⚠ One Pedal Drive System Performance
	PCM		U0415: 00 : 28		<input type="checkbox"/> ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
	PSCM		U0415: 00 : 48		<input type="checkbox"/> ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
	PSCM		U0151: 00 : 08		<input type="checkbox"/> ⚠ Lost Communication With Restraints Control Module
	SOBDM		P0D56: 24 : 68		<input type="checkbox"/> ⚠ Proximity Detection Circuit 'A'
	VDM		U0442: 68 : 28		<input type="checkbox"/> ⚠ Invalid Data Received From ECM/PCM 'B'

Time : 10:23 PM

Odometer :
743 mi

★ CMR		B15E2: 97 : 8F	SSM
ABS		U0253: 00 : 28	TSB
BECM		P2C85: 1E : 6C	
CMR		B15E1: 97 : 0C	SSM
CMR		B115E: 97 : 0C	SSM
GWM		U053B: 57 : 08	
IPC		U0415: 00 : 08	
IPMA		U0501: 86 : 28	
IPMA		B115E: 31 : 28	
IPMA		U0565: 86 : 28	TSB
IPMA		U049A: 86 : 28	
OBCC		U3000: 16 : 68	SSM / TSB
OBCC		P1A3C: 00 : 68	SSM
PCM		P087F: 00 : 28	
PCM		U0415: 00 : 28	
PSCM		U0415: 00 : 48	
PSCM		U0151: 00 : 08	
SOBDM		P0D56: 24 : 68	
VDM		U0442: 68 : 28	

- ⚠ Passenger Side LED
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Hybrid/EV Battery Voltage External Isolation Fault
- ⚠ Driver Side LED
- ⚠ Camera Module
- ⚠ Invalid Data Received From Image Processing Module A
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Invalid Data Received From Door Control Module 'B'
- ⚠ Camera Module
- ⚠ Invalid Data Received From Camera Module-Rear
- ⚠ Invalid Data Received From 'Door Control Module A'
- ⚠ Control Module
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ One Pedal Drive System Performance
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Lost Communication With Restraints Control Module
- ⚠ Proximity Detection Circuit 'A'
- ⚠ Invalid Data Received From ECM/PCM 'B'

Time : 09:13 PM

Odometer :
682 mi

★ BECM		P2C85: 1E : 6C	
★ IPMA		U0565: 86 : 28	TSB
★ SOBDM		P0D56: 24 : 68	
ABS		U0253: 00 : 28	TSB
CMR		B15E1: 97 : 0C	SSM
CMR		B15E2: 97 : 0C	SSM
CMR		B115E: 97 : 0C	SSM
GWM		U053B: 57 : 08	

- ⚠ Hybrid/EV Battery Voltage External Isolation Fault
- ⚠ Invalid Data Received From Camera Module-Rear
- ⚠ Proximity Detection Circuit 'A'
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Driver Side LED
- ⚠ Passenger Side LED
- ⚠ Camera Module
- ⚠ Invalid Data Received From Image Processing Module A

IPC		U0415: 00 : 08		<input type="checkbox"/>	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
IPMA		U0501: 86 : 28		<input type="checkbox"/>	Invalid Data Received From Door Control Module 'B'
IPMA		B115E: 31 : 28		<input type="checkbox"/>	Camera Module
IPMA		U049A: 86 : 28		<input type="checkbox"/>	Invalid Data Received From 'Door Control Module A'
IPMA		U0415: 86 : 28		<input type="checkbox"/>	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
IPMA		B1385: 82 : 28		<input type="checkbox"/>	Lane Keeping Aid System
OBCC		U3000: 16 : 68	SSM / TSB	<input type="checkbox"/>	Control Module
OBCC		P1A3C: 00 : 68	SSM	<input type="checkbox"/>	Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
PCM		P087F: 00 : 28		<input type="checkbox"/>	One Pedal Drive System Performance
PCM		U0415: 00 : 28		<input type="checkbox"/>	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
PSCM		U0415: 00 : 48		<input type="checkbox"/>	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
PSCM		U0151: 00 : 08		<input type="checkbox"/>	Lost Communication With Restraints Control Module
VDM		U0442: 68 : 28		<input type="checkbox"/>	Invalid Data Received From ECM/PCM 'B'

Time : 07:12 PM

Odometer :

574 mi

★ CMR		B115E: 97 : 0C	SSM	<input type="checkbox"/>	Camera Module
★ CMR		B15E2: 97 : 0C	SSM	<input type="checkbox"/>	Passenger Side LED
★ CMR		B15E1: 97 : 0C	SSM	<input type="checkbox"/>	Driver Side LED
★ OBCC		U3000: 16 : 68	SSM / TSB	<input type="checkbox"/>	Control Module
★ PSCM		U0151: 00 : 08		<input type="checkbox"/>	Lost Communication With Restraints Control Module
★ VDM		U0442: 68 : 28		<input type="checkbox"/>	Invalid Data Received From ECM/PCM 'B'
ABS		U0253: 00 : 28	TSB	<input type="checkbox"/>	Lost Communication With Accessory Protocol Interface Module
BECM		P2C85: 1E : 2F		<input type="checkbox"/>	Hybrid/EV Battery Voltage External Isolation Fault
GWM		U053B: 57 : 08		<input type="checkbox"/>	Invalid Data Received From Image Processing Module A
IPC		U0415: 00 : 08		<input type="checkbox"/>	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
IPMA		U0501: 86 : 28		<input type="checkbox"/>	Invalid Data Received From Door Control Module 'B'
IPMA		B115E: 31 : 28		<input type="checkbox"/>	Camera Module
IPMA		U049A: 86 : 28		<input type="checkbox"/>	Invalid Data Received From 'Door Control Module A'
IPMA		U0415: 86 : 28		<input type="checkbox"/>	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
IPMA		B1385: 82 : 28		<input type="checkbox"/>	Lane Keeping Aid System
OBCC		P1A3C: 00 : 68	SSM	<input type="checkbox"/>	Hybrid/EV Battery Charging Disabled - DC Charging Station Performance

PCM		P087F: 00 : 28		<input type="checkbox"/>	One Pedal Drive System Performance
PCM		U0415: 00 : 28		<input type="checkbox"/>	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
PSCM		U0415: 00 : 48		<input type="checkbox"/>	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
SOBDM		POD56: 24 : 28		<input type="checkbox"/>	Proximity Detection Circuit 'A'

Time : 05:40 PM

Odometer :

537 mi

★ BECM		P2C85: 1E : 2F		<input type="checkbox"/>	Hybrid/EV Battery Voltage External Isolation Fault
★ CMR		B115E: 97 : 0E	SSM	<input type="checkbox"/>	Camera Module
★ CMR		B15E2: 97 : 0E	SSM	<input type="checkbox"/>	Passenger Side LED
★ CMR		B15E1: 97 : 0E	SSM	<input type="checkbox"/>	Driver Side LED
★ IPMA		U049A: 86 : 28		<input type="checkbox"/>	Invalid Data Received From 'Door Control Module A'
★ IPMA		U0501: 86 : 28		<input type="checkbox"/>	Invalid Data Received From Door Control Module 'B'
★ PSCM		U0151: 00 : 0A		<input type="checkbox"/>	Lost Communication With Restraints Control Module
★ SOBDM		POD56: 24 : 28		<input type="checkbox"/>	Proximity Detection Circuit 'A'
★ VDM		U0442: 68 : 2E		<input type="checkbox"/>	Invalid Data Received From ECM/PCM 'B'
ABS		U0253: 00 : 28	TSB	<input type="checkbox"/>	Lost Communication With Accessory Protocol Interface Module
GWM		U053B: 57 : 08		<input type="checkbox"/>	Invalid Data Received From Image Processing Module A
IPC		U0415: 00 : 08		<input type="checkbox"/>	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
IPMA		B115E: 31 : 28		<input type="checkbox"/>	Camera Module
IPMA		U0415: 86 : 28		<input type="checkbox"/>	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
IPMA		B1385: 82 : 28		<input type="checkbox"/>	Lane Keeping Aid System
OBCC		P1A3C: 00 : 68	SSM	<input type="checkbox"/>	Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
PCM		P087F: 00 : 28		<input type="checkbox"/>	One Pedal Drive System Performance
PCM		U0415: 00 : 28		<input type="checkbox"/>	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
PSCM		U0415: 00 : 48		<input type="checkbox"/>	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 03:54 PM

Odometer :

465 mi

★ CMR		B115E: 97 : 8F	SSM	<input type="checkbox"/>	Camera Module
★ CMR		B15E2: 97 : 8F	SSM	<input type="checkbox"/>	Passenger Side LED
★ CMR		B15E1: 97 : 8F	SSM	<input type="checkbox"/>	Driver Side LED
★ IPMA		U0501: 86 : 2F		<input type="checkbox"/>	Invalid Data Received From Door Control Module 'B'
★ IPMA		U049A: 86 : 2F		<input type="checkbox"/>	Invalid Data Received From 'Door Control Module A'

★ SOBDM		P0D56: 24 : 68	
ABS		U0253: 00 : 28	TSB
BECM		P2C85: 1E : 6C	
GWM		U053B: 57 : 08	
IPC		U0415: 00 : 08	
IPMA		B115E: 31 : 28	
IPMA		U0415: 86 : 28	
IPMA		B1385: 82 : 28	
OBCC		P1A3C: 00 : 68	SSM
PCM		P087F: 00 : 28	
PCM		U0415: 00 : 28	
PSCM		U0415: 00 : 48	
VDM		U0442: 68 : 28	



- ⚠ Proximity Detection Circuit 'A'
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Hybrid/EV Battery Voltage External Isolation Fault
- ⚠ Invalid Data Received From Image Processing Module A
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Camera Module
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Lane Keeping Aid System
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ One Pedal Drive System Performance
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Invalid Data Received From ECM/PCM 'B'

Time : 03:32 PM
 Odometer :
 465 mi

★ BECM		P2C85: 1E : 6C	
★ OBCC		P1A3C: 00 : 68	SSM
★ VDM		U0442: 68 : 28	
ABS		U0253: 00 : 28	TSB
CMR		B15E1: 97 : 08	SSM
CMR		B15E2: 97 : 08	SSM
CMR		B115E: 97 : 08	SSM
GWM		U053B: 57 : 08	
IPC		U0415: 00 : 08	
IPMA		B115E: 31 : 28	
IPMA		U0415: 86 : 28	
IPMA		B1385: 82 : 28	
PCM		P087F: 00 : 28	
PCM		U0415: 00 : 28	

- ⚠ Hybrid/EV Battery Voltage External Isolation Fault
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Invalid Data Received From ECM/PCM 'B'
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Driver Side LED
- ⚠ Passenger Side LED
- ⚠ Camera Module
- ⚠ Invalid Data Received From Image Processing Module A
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Camera Module
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Lane Keeping Aid System
- ⚠ One Pedal Drive System Performance
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

PSCM | U0415: 00 : 48
SOBDM | P0D56: 24 : 28

 Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
  Proximity Detection Circuit 'A'

Time : 01:58 PM
Odometer :
385 mi

★ **BECM** | **P2C85: 1E : 2F**
★ CMR | B115E: 97 : 08 SSM
★ CMR | B15E2: 97 : 08 SSM
★ CMR | B15E1: 97 : 08 SSM
★ IPMA | B115E: 31 : 28
ABS | U0253: 00 : 28 TSB

GWM | U053B: 57 : 08

IPC | U0415: 00 : 08







IPMA | U0415: 86 : 28


IPMA | B1385: 82 : 28
PCM | P087F: 00 : 28
PCM | U0415: 00 : 28


PSCM | U0415: 00 : 48


SOBDM | P0D56: 24 : 28



VDM | U0442: 68 : 2C


 Hybrid/EV Battery Voltage External Isolation Fault
  Camera Module
  Passenger Side LED
  Driver Side LED
  Camera Module
  Lost Communication With Accessory Protocol Interface Module


  Invalid Data Received From Image Processing Module A


  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'


  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

  Lane Keeping Aid System
  One Pedal Drive System Performance

  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

  Proximity Detection Circuit 'A'

  Invalid Data Received From ECM/PCM 'B'

Time : 09:32 PM

Odometer :
285 mi

★ IPMA		B115E: 31 : 2C	
★ SOBDM		P0D56: 24 : 28	
★ VDM		U0442: 68 : 2C	
ABS		U0253: 00 : 28	TSB
CMR		B15E1: 97 : 0C	SSM
CMR		B15E2: 97 : 0C	SSM
CMR		B115E: 97 : 0C	SSM
GWM		U053B: 57 : 08	
IPC		U0415: 00 : 08	
IPMA		U0415: 86 : 28	
IPMA		B1385: 82 : 28	
PCM		P087F: 00 : 28	
PCM		U0415: 00 : 28	
PSCM		U0415: 00 : 48	

- ⚠ Camera Module
- ⚠ Proximity Detection Circuit 'A'
- ⚠ Invalid Data Received From ECM/PCM 'B'
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Driver Side LED
- ⚠ Passenger Side LED
- ⚠ Camera Module
- ⚠ Invalid Data Received From Image Processing Module A
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Lane Keeping Aid System
- ⚠ One Pedal Drive System Performance
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'


Time : 08:39 PM

Odometer :
267 mi

★ ABS		U0253: 00 : 28	TSB
★ CMR		B115E: 97 : 0C	SSM
★ CMR		B15E2: 97 : 0C	SSM
★ CMR		B15E1: 97 : 0C	SSM
★ SOBDM		P0D56: 24 : 68	
GWM		U053B: 57 : 08	
IPC		U0415: 00 : 08	
IPMA		U0415: 86 : 28	
IPMA		B1385: 82 : 28	
PCM		P087F: 00 : 28	
PCM		U0415: 00 : 28	

- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Proximity Detection Circuit 'A'
- ⚠ Invalid Data Received From Image Processing Module A
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Lane Keeping Aid System
- ⚠ One Pedal Drive System Performance
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

PSCM | U0415: 00 : 48

 Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 01:09 PM

Odometer :

60 mi

★ SOBDM | P0D56: 24 : 28

CMR | B15E1: 97 : 08 SSM

CMR | B15E2: 97 : 08 SSM

CMR | B115E: 97 : 08 SSM

GWM | U053B: 57 : 08

IPC | U0415: 00 : 08

IPMA | U0415: 86 : 28


IPMA | B1385: 82 : 28

PCM | P087F: 00 : 28

PCM | U0415: 00 : 28


PSCM | U0415: 00 : 48


 Proximity Detection Circuit 'A'


 Driver Side LED

 Passenger Side LED

 Camera Module


 Invalid Data Received From Image Processing Module A


 Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

 Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

 Lane Keeping Aid System

 One Pedal Drive System Performance

 Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

 Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

March 31, 2024

Time : 05:13 PM

Odometer :

57 mi

CMR | B15E1: 97 : 08 SSM

PCM | P087F: 00 : 28

GWM | U053B: 57 : 08

PCM | U0415: 00 : 28

CMR | B15E2: 97 : 08 SSM

PSCM | U0415: 00 : 48

IPC | U0415: 00 : 08

IPMA | U0415: 86 : 28


CMR | B115E: 97 : 08 SSM


IPMA | B1385: 82 : 28


Select All


 Driver Side LED


 One Pedal Drive System Performance


 Invalid Data Received From Image Processing Module A

 Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

 Passenger Side LED

 Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

 Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

 Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

 Camera Module

 Lane Keeping Aid System

Time : 12:12 AM

Odometer :

52 mi

★	GWM		U053B: 57 : 08	
	ABS		C0051: 67 : 28	
	CMR		B15E1: 97 : 08	SSM
	CMR		B15E2: 97 : 08	SSM
	CMR		B115E: 97 : 08	SSM
	IPC		U0415: 00 : 08	
	IPMA		U0415: 86 : 28	
	IPMA		B1385: 82 : 28	
	PCM		P087F: 00 : 28	
	PCM		U0415: 00 : 28	
	PSCM		U0415: 00 : 48	

- ⚠ Invalid Data Received From Image Processing Module A
- ⚠ Steering Wheel Position Sensor
- ⚠ Driver Side LED
- ⚠ Passenger Side LED
- ⚠ Camera Module
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Lane Keeping Aid System
- ⚠ One Pedal Drive System Performance
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 10:11 PM

Odometer :
44 mi

★ GWM		U053B : 57 : 0B	
ABS		C0051 : 67 : 28	
ABS		U0131 : 00 : 28	
CMR		B15E1 : 97 : 08	SSM
CMR		B15E2 : 97 : 08	SSM
CMR		B115E : 97 : 08	SSM
IPC		U0415 : 00 : 08	
IPMA		U0415 : 86 : 28	
IPMA		B1385 : 82 : 28	
PCM		P087F : 00 : 28	
PCM		U0415 : 00 : 28	
PSCM		U0415 : 00 : 48	

- ⚠ Invalid Data Received From Image Processing Module A
- ⚠ Steering Wheel Position Sensor
- ⚠ Lost Communication With Power Steering Control Module 'A'
- ⚠ Driver Side LED
- ⚠ Passenger Side LED
- ⚠ Camera Module
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Lane Keeping Aid System
- ⚠ One Pedal Drive System Performance
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 08:11 PM

Odometer :
36 mi

CMR		B15E1 : 97 : 08	SSM
PCM		P087F : 00 : 28	
PCM		U0415 : 00 : 28	
CMR		B15E2 : 97 : 08	SSM
ABS		U0131 : 00 : 28	
PSCM		U0415 : 00 : 48	
IPC		U0415 : 00 : 08	
IPMA		U0415 : 86 : 28	
ABS		C0051 : 67 : 28	
CMR		B115E : 97 : 08	SSM
IPMA		B1385 : 82 : 28	

- ⚠ Driver Side LED
- ⚠ One Pedal Drive System Performance
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Passenger Side LED
- ⚠ Lost Communication With Power Steering Control Module 'A'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- ⚠ Steering Wheel Position Sensor
- ⚠ Camera Module
- ⚠ Lane Keeping Aid System