

PASO ROBLES FORD



"The People's Choice"

2401 Oakwood Street • Paso Robles, CA 93446

(805) 239-3673 FAX (805) 239-0531

www.pasoroblesford.com • service@pasoroblesford.com

SO # 525085

SERVICE ORDER



Printed 09/15/2021 10:51:51 AM **CUSTOMER COPY - ** IN PROGRESS **** User 83 Page 1

Customer No	BONO3	Advisor	Adam Becker	Promised	09/03/2021 5:00 PM	Tag	y386
John Bono		Shop	S1	Opened	09/03/2021 4:38 PM	Location	
11275 Eliano St		Priority	15	Cashiered		PO #	525085
Atascadero, CA 93422							

Home (805) 550-6999 **Bus**
Cell (805) 235-3906 **Today** (805) 550-6999
Email sbono@charter.net

Term CASH

License No		Odometer In	386	Odometer Out	388	InServ Date	08/27/2021	Stock No	M6710
Year	2021	Make	FORD	Model	MUSTANG MACH-E	Model No	K1S	Color	SPACE WHITE
Vehicle ID No	3FMTK1SS3MMA41765	Selling Dealer	PASO ROBLES	Extended Warranty	FORD ESP	Delivery Date	08/27/2021		
Engine Size	RR PRIMARY & FR SECONDARY	Fleet #							

Request	Description	Job	CSR	Status
M	TOW IN - CUST STATES MESSAGE FOR PULL OVER SAFELY AND SHUT OFF CAME ON. WILL NOT START. CHECK/ADVISE	1	83	Original

Labor	Description	Type	Amount
		W	

Part	Description	Shp	Bin	Type	Retail	Price	Amount
LJ9Z 10C666 A	CONNECTOR	1	NEW	W			
W720752 S450L	SCREW	24	NEW	W			
W520111 S450B	NUT	8	SOP5	W			
LJ9Z 10A815 A	GASKET - H/V BATTERY VENT COVE	1	NEW	W			
W720869 S450	BOLT - HEX.HEAD	8	NEW	W			
W720894 S450	BOLT - HEX.HEAD	8	NEW	W			
VC 13DL G	ANTI-FREEZE	1	106	W			

Technician 90 - Chris Stober Parts Total 0.00

Cause FDRS DIAG U3012 BECM,U0100 GFM U0293 GFM,B1578IPMA,P1A10 SOBDMC, U045A SOBDMCP07E4 SOBDMC, P07E6 SOBDMC. PERFORM PPT R CHECK RESISTANCE BECM LEAKAGE IN BATTERIES FAIL CONTACT HOTLINE CONTINUE PPT R DIS CONNECT HV CABLES FROM SOBDM B AND SOBDMC TEST CABLES FOR SHORT PASS.. HOTLINE CONTACTED ME REPORT ATTACHED SAID TO REPLACE HV BJB IN BATTERY PACK. Labor Total 0.00

Correction REMOVE HV BATTERY DISASSEMBLE AND REPLACE HV BJB REASSEMBLE BATTERY PERFORM LEAK CHECK PASS REINSTALL CLEAR CODES RETEST FAIL STILL DISABLEING HV BATTERY CODES RETURNING. MONITORING RESISTANCE PIDS THEY ARE VARYING. DISCONNECT ALL HV BATTERY CONNECTORS CLEAN WITH ELECTRONICS CLEANER REASSEMBLE RETEST PASS HV BATTERY NOW ENABLED. CODE B1578 IPMA STILL THERE PERFORM PPT FOR CODE SAYS TO CALIBRATE 360 DEGREE CAMERA PERFORM 20 MINUTE ROAD TEST TO CALIBRATE CALIBRATION SUCCESSFUL CLEAR CODES RETEST PASS Request Total 0.00

B.A.R. # ARD 153520

PARTS ARE NEW UNLESS OTHERWISE SPECIFIED

E.P.A. # CAL 0317446

VEHICLES CAN NOT BE RELEASED AFTER SERVICE DEPT. HOURS
 Thank you for this opportunity to serve you. It is our aim to perform all the repairs requested on this repair order to your complete satisfaction. If you have any question pertaining to this work order please contact your service advisor

NOTICE TO CONSUMER:

PLEASE READ IMPORTANT INFORMATION IN TERMS, BELOW
 By law, you may choose another Licensed Smog Check facility to perform any needed repairs or adjustments which the Smog Check Test indicates are necessary.

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE.

Date: _____ Customer Signature: _____

**Thank
 you for
 your
 business!**