

Case: 1 Engine Electrical

,, when put on ac charger, get charger faults (get messages on Ford App). guest also feels 12v is drained (had message about draw)

Quantity Description/Correction

Price Total
\$0.00 \$0.00

- Tech Cause: checked with charger and working scanned p1a10 pinpoint test ay1 erase code and let sit for 5 mins and scann again
- Tech Comments: scanned again after 5 mins and no codes present all working at this time - Warranty