

Last Vehicle Status Update: April 28, 2024 10:50 PM

*Note: Do not use as a pressure gauge

Refresh

Odometer



18961 Miles

High Voltage Battery



Battery State of Charge : 70%

Battery Range : 199 Miles

Tire Pressure (PSI)*



Recommended Tire Pressure(cold)

Front : 39 | Rear : 39

Last Vehicle Health Update: April 28, 2024 08:42 PM

February 2024

Sun	Mon	Tue	Wed	Thu
				1
4	5	6	7	8
11	12	13	14	15
18	19	20	21	22
25	26	27	28	29

March 2024

Sun	Mon	Tue	Wed	Thu
3	4	5	6	7
10	11	12	13	14
17	18	19	20	21
24	25	26	27	28

April 2024

Sun	Mon	Tue	Wed	Thu
	1	2	3	4
7	8	9	10	11
17	18	19	20	21
21	22	23	24	25
28	29	30		

Vehicle Health Alerts (VHA) and Diagnostic Trouble Codes (DTC)

Date Time Odometer	Event Description	Module	DTC	FT : SB	TSB/GSB/SSM	Send to Search	Description
------------------------	-------------------	--------	-----	---------	-------------	----------------	-------------

April 28, 2024

Time : 08:42 PM
Odometer : 18958 mi

CMR		B15E1 : 97 : 0C	SSM
RFA		U200D : 15 : 48	SSM
IPMA		U0253 : 00 : 2C	
GFM		U0100 : 00 : 08	TSB
RFA		U200F : 15 : 48	SSM
CMR		B15E2 : 97 : 0C	SSM
CMR		B115E : 97 : 0C	SSM
RFA		U200E : 15 : 48	SSM

Select All

- Driver Side LED
- Control Module Output Power A
- Lost Communication With Accessory Protocol Interface Module
- Lost Communication With ECM/PCM 'A'
- Control Module Output Power C
- Passenger Side LED
- Camera Module
- Control Module Output Power B

April 27, 2024

Select All

Time : 11:21 PM

Odometer :
18920 mi

★	IPMA		U0253: 00 : 2C	
	CMR		B15E1: 97 : 0C	SSM
	CMR		B15E2: 97 : 0C	SSM
	CMR		B115E: 97 : 0C	SSM
	GFM		U0100: 00 : 08	TSB
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	RFA		U200E: 15 : 48	SSM

- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Driver Side LED
- ⚠ Passenger Side LED
- ⚠ Camera Module
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B

April 25, 2024

Select All

Time : 12:00 PM

Odometer :
18894 mi

	CMR		B15E1: 97 : 0C	SSM
	RFA		U200D: 15 : 48	SSM
	GFM		U0100: 00 : 08	TSB
	RFA		U200F: 15 : 48	SSM
	CMR		B15E2: 97 : 0C	SSM
	CMR		B115E: 97 : 0C	SSM
	RFA		U200E: 15 : 48	SSM

- ⚠ Driver Side LED
- ⚠ Control Module Output Power A
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Control Module Output Power C
- ⚠ Passenger Side LED
- ⚠ Camera Module
- ⚠ Control Module Output Power B

April 24, 2024

Select All

Time : 12:04 PM

Odometer :
18838 mi

★	CMR		B115E: 97 : 0C	SSM
★	CMR		B15E2: 97 : 0C	SSM
★	CMR		B15E1: 97 : 0C	SSM
	GFM		U0100: 00 : 08	TSB
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	RFA		U200E: 15 : 48	SSM

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B

April 23, 2024

Select All

Time : 09:45 PM

Odometer :
18827 mi

RFA		U200D: 15 : 48	SSM
GFM		U0100: 00 : 08	TSB
RFA		U200F: 15 : 48	SSM
RFA		U200E: 15 : 48	SSM

- ⚠ Control Module Output Power A
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B

April 22, 2024

Select All

Time : 01:45 AM

Odometer :
18801 mi

CMR		B15E1: 97 : 0C	SSM
SOBDMC		U0100: 00 : 28	TSB
IPMA		U0565: 82 : 28	
RFA		U200D: 15 : 48	SSM
SOBDMB		U0100: 00 : 28	TSB
GFM		U0100: 00 : 08	TSB
RFA		U200F: 15 : 48	SSM
IPMA		U0253: 00 : 28	
OBCC		P1A3C: 00 : 68	SSM
CMR		B15E2: 97 : 0C	SSM
CMR		B115E: 97 : 0C	SSM
RFA		U200E: 15 : 48	SSM

- ⚠ Driver Side LED
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Invalid Data Received From Camera Module-Rear
- ⚠ Control Module Output Power A
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Control Module Output Power C
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Passenger Side LED
- ⚠ Camera Module
- ⚠ Control Module Output Power B

Time : 10:04 PM

Odometer :
18754 mi

★	CMR		B115E: 97 : 0C	SSM
★	CMR		B15E2: 97 : 0C	SSM
★	CMR		B15E1: 97 : 0C	SSM
★	IPMA		U0565: 82 : 28	
	ABS		U0293: 00 : 28	TSB
	ABS		U0100: 00 : 28	TSB
	GFM		U0100: 00 : 08	TSB
	IPMA		U0253: 00 : 28	
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	RFA		U200E: 15 : 48	SSM
	SOBDMB		U0100: 00 : 28	TSB
	SOBDMC		U0100: 00 : 28	TSB

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Invalid Data Received From Camera Module-Rear
- ⚠ Lost Communication With Hybrid/EV Powertrain Control Module 'A'
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With ECM/PCM 'A'

Time : 01:37 PM

Odometer :
18734 mi

★	CMR		B115E: 97 : 08	SSM
★	CMR		B15E2: 97 : 08	SSM
★	CMR		B15E1: 97 : 08	SSM
★	RFA		U200E: 15 : 48	SSM
★	SOBDMC		U0100: 00 : 28	TSB
	ABS		U0293: 00 : 28	TSB
	ABS		U0100: 00 : 28	TSB
	GFM		U0100: 00 : 08	TSB
	IPMA		U0253: 00 : 28	
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	SOBDMB		U0100: 00 : 28	TSB

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Control Module Output Power B
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With Hybrid/EV Powertrain Control Module 'A'
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Lost Communication With ECM/PCM 'A'

Time : 10:21 PM

Odometer :
18705 mi

★	ABS		U0100: 00 : 28	TSB
★	ABS		U0293: 00 : 28	TSB
★	CMR		B115E: 97 : 0E	SSM
★	CMR		B15E2: 97 : 0E	SSM
★	CMR		B15E1: 97 : 0E	SSM
★	IPMA		U0253: 00 : 28	
★	RFA		U200E: 15 : 0A	SSM
★	SOBDMB		U0100: 00 : 28	TSB
★	SOBDMC		U0100: 00 : 2C	TSB
	ABS		U0253: 00 : 28	TSB
	GFM		U0100: 00 : 08	TSB
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM

- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With Hybrid/EV Powertrain Control Module 'A'
- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Control Module Output Power B
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C

Time : 02:25 PM

Odometer :
18676 mi

★	CMR		B15E2: 97 : 08	SSM
★	CMR		B15E1: 97 : 08	SSM
★	CMR		B115E: 97 : 08	SSM
★	IPMA		U0253: 00 : 2C	
	ABS		U0253: 00 : 28	TSB
	GFM		U0100: 00 : 08	TSB
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200E: 15 : 48	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM

- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Camera Module
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power B
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C

Time : 12:06 AM

Odometer :
18647 mi

★	ABS		U0253: 00 : 28	TSB
★	CMR		B115E: 97 : 0C	SSM
★	CMR		B15E2: 97 : 0C	SSM
★	CMR		B15E1: 97 : 0C	SSM
	GFM		U0100: 00 : 08	TSB
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	RFA		U200E: 15 : 48	SSM

- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B

Time : 06:11 PM

Odometer :
18632 mi

★	ABS		U0253: 00 : 2F	TSB
	CMR		B15E1: 97 : 0E	SSM
	CMR		B15E2: 97 : 0E	SSM
	CMR		B115E: 97 : 0E	SSM
	GFM		U0100: 00 : 08	TSB
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	RFA		U200E: 15 : 48	SSM

- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Driver Side LED
- ⚠ Passenger Side LED
- ⚠ Camera Module
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B

Time : 05:14 PM

Odometer :
18623 mi

★	CMR		B115E: 97 : 0E	SSM
★	CMR		B15E2: 97 : 0E	SSM
★	CMR		B15E1: 97 : 0E	SSM
★	RFA		U200E: 15 : 48	SSM
	GFM		U0100: 00 : 08	TSB
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Control Module Output Power B
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C

Time : 11:19 PM

Odometer :
18608 mi

★	CMR		B115E: 97 : 0C	SSM
★	CMR		B15E2: 97 : 0C	SSM
★	CMR		B15E1: 97 : 0C	SSM
★	RFA		U200E: 15 : 0A	SSM
	GFM		U0100: 00 : 08	TSB
	IPMA		U0253: 00 : 28	
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Control Module Output Power B
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C

Time : 07:14 PM

Odometer :
18570 mi

	CMR		B15E1: 97 : 08	SSM
	CMR		B15E2: 97 : 08	SSM
	RFA		U200D: 15 : 48	SSM
	GFM		U0100: 00 : 08	TSB
	RFA		U200F: 15 : 48	SSM
	IPMA		U0253: 00 : 28	
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200E: 15 : 48	SSM
	CMR		B115E: 97 : 08	SSM

- ⚠ Driver Side LED
- ⚠ Passenger Side LED
- ⚠ Control Module Output Power A
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Control Module Output Power C
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power B
- ⚠ Camera Module

Time : 05:11 PM

Odometer :
18559 mi

★	CMR		B15E1: 97 : 08	SSM
	CMR		B15E2: 97 : 08	SSM
	CMR		B115E: 97 : 08	SSM
	GFM		U0100: 00 : 08	TSB
	IPMA		U0253: 00 : 28	
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	RFA		U200E: 15 : 48	SSM

- ⚠ Driver Side LED
- ⚠ Passenger Side LED
- ⚠ Camera Module
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B

Time : 01:22 PM

Odometer :

18526 mi

★	CMR		B115E: 97 : 08	SSM
★	CMR		B15E2: 97 : 08	SSM
★	CMR		B15E1: 97 : 0C	SSM
	GFM		U0100: 00 : 08	TSB
	IPMA		U0253: 00 : 28	
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	RFA		U200E: 15 : 48	SSM

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B

April 11, 2024

Time : 10:15 PM

Odometer :

18501 mi

	RFA		U200F: 15 : 48	SSM
	IPMA		U0253: 00 : 28	
	OBCC		P1A3C: 00 : 68	SSM
	CMR		B15E2: 97 : 8F	SSM
	RFA		U200E: 15 : 48	SSM
	CMR		B115E: 97 : 8F	SSM
	CMR		B15E1: 97 : 8F	SSM
	RFA		U200D: 15 : 48	SSM
	GFM		U0100: 00 : 08	TSB

- Select All
- ⚠ Control Module Output Power C
- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Passenger Side LED
- ⚠ Control Module Output Power B
- ⚠ Camera Module
- ⚠ Driver Side LED
- ⚠ Control Module Output Power A
- ⚠ Lost Communication With ECM/PCM 'A'

April 03, 2024

Select All

Time : 06:30 PM

Odometer :
18253 mi

★	IPMA		U0253: 00 : 28	
	CMR		B15E1: 97 : 8F	SSM
	CMR		B15E2: 97 : 8F	SSM
	CMR		B115E: 97 : 8F	SSM
	GFM		U0100: 00 : 08	TSB
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	RFA		U200E: 15 : 48	SSM

- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Driver Side LED
- ⚠ Passenger Side LED
- ⚠ Camera Module
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B

April 02, 2024

Select All

Time : 09:22 PM

Odometer :
18219 mi

★	CMR		B115E: 97 : 8F	SSM
★	CMR		B15E2: 97 : 8F	SSM
★	CMR		B15E1: 97 : 8F	SSM
	GFM		U0100: 00 : 08	TSB
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	RFA		U200E: 15 : 48	SSM

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B

March 30, 2024

Select All

Time : 10:28 PM

Odometer :
18133 mi

★	CMR		B115E: 97 : 0C	SSM
★	CMR		B15E2: 97 : 0C	SSM
★	CMR		B15E1: 97 : 0C	SSM
★	RFA		U200E: 15 : 48	SSM
	GFM		U0100: 00 : 08	TSB
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Control Module Output Power B
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C

March 27, 2024

Select All

Time : 01:38 PM

Odometer :
17973 mi

★	ABS		U0253: 00 : 2F	TSB
	CMR		B15E1: 97 : 08	SSM
	CMR		B15E2: 97 : 08	SSM
	CMR		B115E: 97 : 08	SSM
	GFM		U0100: 00 : 08	TSB
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200E: 15 : 0A	SSM
	RFA		U200F: 15 : 48	SSM

- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Driver Side LED
- ⚠ Passenger Side LED
- ⚠ Camera Module
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power B
- ⚠ Control Module Output Power C

Time : 01:04 PM

Odometer :
17943 mi

★	RFA		U200E: 15 : 0A	SSM
	CMR		B15E1: 97 : 08	SSM
	CMR		B15E2: 97 : 08	SSM
	CMR		B115E: 97 : 08	SSM
	GFM		U0100: 00 : 08	TSB
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM

- ⚠ Control Module Output Power B
- ⚠ Driver Side LED
- ⚠ Passenger Side LED
- ⚠ Camera Module
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C

March 23, 2024

Select All

Time : 07:34 PM

Odometer :
17902 mi

★	ABS		U0253: 00 : 28	TSB
★	CMR		B115E: 97 : 08	SSM
★	CMR		B15E2: 97 : 08	SSM
★	CMR		B15E1: 97 : 08	SSM
★	GFM		U0100: 00 : 08	TSB
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	RFA		U200E: 15 : 48	SSM

- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B

Time : 04:26 PM

Odometer :
17881 mi

★	CMR		B115E: 97 : 0C	SSM
★	CMR		B15E2: 97 : 0C	SSM
★	CMR		B15E1: 97 : 0C	SSM
★	GFM		U0100: 00 : 0A	TSB
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	RFA		U200E: 15 : 48	SSM

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Lost Communication With ECM/PCM 'A'
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B

March 22, 2024

Select All

Time : 12:59 PM

Odometer :
17858 mi

★	ABS		U0253: 00 : 28	TSB
★	CMR		B15E2: 97 : 08	SSM
★	CMR		B15E1: 97 : 0E	SSM
	CMR		B115E: 97 : 08	SSM
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	RFA		U200E: 15 : 48	SSM

- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Camera Module
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B

March 19, 2024

Select All

Time : 09:46 PM

Odometer :
17804 mi

★	ABS		U0253: 00 : 2F	TSB
★	CMR		B15E2: 97 : 0E	SSM
	CMR		B15E1: 97 : 08	SSM
	CMR		B115E: 97 : 08	SSM
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	RFA		U200E: 15 : 48	SSM

- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Camera Module
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B

March 17, 2024

Select All

Time : 12:31 PM

Odometer :
17740 mi

★	CMR		B115E: 97 : 08	SSM
★	CMR		B15E2: 97 : 08	SSM
★	CMR		B15E1: 97 : 08	SSM
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	RFA		U200E: 15 : 48	SSM

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B

Time : 12:10 AM

Odometer :
17717 mi

★	CMR		B115E: 97 : 0C	SSM
★	CMR		B15E2: 97 : 0C	SSM
★	CMR		B15E1: 97 : 0C	SSM
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	RFA		U200E: 15 : 48	SSM

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B









March 16, 2024

Select All

Time : 08:24 PM

Odometer :
17696 mi

CMR		B15E1: 97 : 08	SSM
IPMA		B115E: 31 : 28	
CMR		B15E2: 97 : 08	SSM
RFA		U200D: 15 : 48	SSM
RFA		U200F: 15 : 48	SSM
OBCC		P1A3C: 00 : 68	SSM
RFA		U200E: 15 : 48	SSM
CMR		B115E: 97 : 08	SSM

-  Driver Side LED
-  Camera Module
-  Passenger Side LED
-  Control Module Output Power A
-  Control Module Output Power C
-  Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
-  Control Module Output Power B
-  Camera Module









March 15, 2024

Select All

Time : 11:09 PM

Odometer :
17656 mi

★ CMR		B15E2: 97 : 08	SSM
CMR		B115E: 97 : 08	SSM
CMR		B15E1: 97 : 08	SSM
IPMA		B115E: 31 : 28	
OBCC		P1A3C: 00 : 68	SSM
RFA		U200F: 15 : 48	SSM
RFA		U200E: 15 : 48	SSM
RFA		U200D: 15 : 48	SSM

-  Passenger Side LED
-  Camera Module
-  Driver Side LED
-  Camera Module
-  Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
-  Control Module Output Power C
-  Control Module Output Power B
-  Control Module Output Power A









March 14, 2024

Select All

Time : 05:41 PM

Odometer :
17632 mi

★ CMR		B15E2: 97 : 0C	SSM
CMR		B15E1: 97 : 08	SSM
CMR		B115E: 97 : 08	SSM
IPMA		B115E: 31 : 28	
OBCC		P1A3C: 00 : 68	SSM
RFA		U200D: 15 : 48	SSM
RFA		U200F: 15 : 48	SSM
RFA		U200E: 15 : 48	SSM

-  Passenger Side LED
-  Driver Side LED
-  Camera Module
-  Camera Module
-  Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
-  Control Module Output Power A
-  Control Module Output Power C
-  Control Module Output Power B









March 13, 2024

Select All

Time : 05:33 PM

Odometer :
17618 mi

CMR		B15E1: 97 : 08	SSM
IPMA		B115E: 31 : 28	
CMR		B15E2: 97 : 08	SSM
RFA		U200D: 15 : 48	SSM
RFA		U200F: 15 : 48	SSM
OBCC		P1A3C: 00 : 68	SSM
RFA		U200E: 15 : 48	SSM
CMR		B115E: 97 : 08	SSM

-  Driver Side LED
-  Camera Module
-  Passenger Side LED
-  Control Module Output Power A
-  Control Module Output Power C
-  Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
-  Control Module Output Power B
-  Camera Module









March 07, 2024

Select All

Time : 08:58 PM

Odometer :
17579 mi

CMR		B15E1: 97 : 08	SSM
IPMA		B115E: 31 : 28	
CMR		B15E2: 97 : 08	SSM
RFA		U200D: 15 : 48	SSM
RFA		U200F: 15 : 48	SSM
OBCC		P1A3C: 00 : 68	SSM
RFA		U200E: 15 : 48	SSM
CMR		B115E: 97 : 08	SSM

-  Driver Side LED
-  Camera Module
-  Passenger Side LED
-  Control Module Output Power A
-  Control Module Output Power C
-  Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
-  Control Module Output Power B
-  Camera Module

March 06, 2024

Select All

Time : 01:04 PM

Odometer :
17549 mi

★	ABS		U0253: 00 : 28	TSB
	CMR		B15E1: 97 : 08	SSM
	CMR		B15E2: 97 : 08	SSM
	CMR		B115E: 97 : 08	SSM
	IPMA		B115E: 31 : 28	
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	RFA		U200E: 15 : 48	SSM

- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Driver Side LED
- ⚠ Passenger Side LED
- ⚠ Camera Module
- ⚠ Camera Module
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B

March 01, 2024

Select All

Time : 07:20 PM

Odometer :
17438 mi

★	ABS		U0253: 00 : 2C	TSB
★	IPMA		B115E: 31 : 28	
	CMR		B15E1: 97 : 08	SSM
	CMR		B15E2: 97 : 08	SSM
	CMR		B115E: 97 : 08	SSM
	HVAC		B162E: 01 : 08	
	OBCC		P1A3C: 00 : 68	SSM
	RFA		U200D: 15 : 48	SSM
	RFA		U200F: 15 : 48	SSM
	RFA		U200E: 15 : 48	SSM

- ⚠ Lost Communication With Accessory Protocol Interface Module
- ⚠ Camera Module
- ⚠ Driver Side LED
- ⚠ Passenger Side LED
- ⚠ Camera Module
- ⚠ Max Defrost LED
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power A
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power B

Time : 09:02 PM

Odometer :

17416 mi

★	CMR		B115E: 97 : 08	SSM
★	CMR		B15E2: 97 : 08	SSM
★	CMR		B15E1: 97 : 08	SSM
★	HVAC		B162E: 01 : 08	
★	IPMA		B115E: 31 : 2E	
★	OBCC		P1A3C: 00 : 68	SSM
★	RFA		U200E: 15 : 48	SSM
★	RFA		U200F: 15 : 48	SSM
★	RFA		U200D: 15 : 48	SSM

- ⚠ Camera Module
- ⚠ Passenger Side LED
- ⚠ Driver Side LED
- ⚠ Max Defrost LED
- ⚠ Camera Module
- ⚠ Hybrid/EV Battery Charging Disabled - DC Charging Station Performance
- ⚠ Control Module Output Power B
- ⚠ Control Module Output Power C
- ⚠ Control Module Output Power A