



Direct Parts:

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ \_\_\_\_\_ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

Form with fields: H.S.T. VENDOR NO. 12061 0993 RT0001, ALL ITEMS ARE SUBJECT TO H.S.T., CUSTOMER NO. 266021, ADVISOR, TAG NO. 581, INVOICE DATE 08/26/25, INVOICE NO. FCCS477962, LABOUR RATE 170.00, LICENSE NO., KILOMETRES 33,276, COLOUR CARBONIZED, STOCK NO. 21000, YEAR/MAKE/MODEL 21/FORD/MUSTANG/MACH-E PREMIUM AWD, DELIVERY DATE 02/09/21, DELIVERY KMS. 10, VEHICLE I.D. NO. 3 F M T K 3 S U 6 M M A 0 1 5 8 1, SELLING DEALER NO., PRODUCTION DATE, F.T.E. NO., P.O. NO., R.O. DATE 05/22/25, IN SERVICE DATE, RESIDENCE PHONE, BUSINESS PHONE, COMMENTS.

MO: 33276

JOB# 1 CHARGES-----
LABOR-----
J# 1 10FOZZ10 AVR TEST HOURS: 0.50 TECH(S):8947 INTERNAL
COMPLAINT: DIAG VEHICLE WILL NOT CHARGE AT ITS RATED CAPACITY.IT IS CHARGING TOO SLOW NOW MATTER WHAT CHARGING STATION IS USED. IT CHAGES AS LOW AS 2.2 AMPS AND FLUCTUATES AROUND AND NEVER GOES OVER 30 AMPS AND DOES NOT STAY THERE FOR LONG. THIS STARTED HAPPENING APTER AN UPDATE IN JUNE OF 2023.
CORRECTION: INSPECT FOR CUSTOMER CONCERN. CONTACTED FORD HOTLINE. RECOMMENDED THAT DUE TO CURRENT SOFTWARE, THIS IS A NORMAL CHARACTERISTIC OF THE VEHICLE NOW.
JOB# 1 TOTALS-----
JOB# 1 JOURNAL PREFIX FCCS JOB# 1 TOTAL 0.00

ALMOST OUT OF WARRANTY?
Ford EXTENDED SERVICE PLAN
ASK FOR DETAILS



FORD SERVICE



TAX SUMMARY-----
HST 0.00 R-120610993
TOTALS-----
\*\*\*\*\*
\* AMEX [ ] CASH [ ] \*
\* CHARGE [ ] CHEQUE [ ] \*
\* DBT/CRD [ ] MST/CRD [ ] \*
\* VISA [ ] OTHER [ ] \*
\*\*\*\*\*
TOTAL LABOR.... 0.00
TOTAL PARTS.... 0.00
TOTAL SUBLET... 0.00
TOTAL G.O.G.... 0.00
TOTAL MISC CHG. 0.00
TOTAL MISC DISC 0.00
TOTAL TAX..... 0.00
TOTAL INVOICE \$ 0.00

The Consumer Protection Act, 2002 provides you with rights in relation to having a motor vehicle repaired. Among other things, you have a right to a written estimate. A repairer may not charge an amount that is more than ten (10) percent above that estimate. If you waived your right to an estimate, the repairer must have your authorization of the maximum amount that you will pay for the repairs. The repairer may not charge more than the maximum amount you authorized. In either case, the repairer may not charge for any work you did not authorize.

If you have concerns about the work or repairs performed by the repairer or about your rights or duties under the Consumer Protection Act, 2002, you should contact the Ministry of Consumer and Business Services.

Thank you for allowing us to service your vehicle. Our goal is to ensure a convenient and completely satisfied experience. If you are not 100% satisfied, please contact our service department immediately. Please see reverse side for important privacy, retail purchase and warranty information.

Thank You

PLEASE RETURN FOR A FREE WHEEL
RE-TORQUE AFTER 160 KMS OF DRIVING.
RECOMMENDED WHEN WHEELS HAVE BEEN REMOVED.

CUSTOMER SIGNATURE

ELC-S11 (9-98) Copyright © 1985 The Reynolds and Reynolds Company (Canada) LTD. SF690405 Q. (02/17)